



TOP VIEW
OUTLINE




TOP VIEW
TOP METAL




TOP VIEW
BOTTOM METAL



TOP VIEW
TOP SOLDERMASK



TOP VIEW
TOP SILK SCREEN



NOTES:

- 9. HOLES MARKED '▲' ARE NON PLATED THRU (7 PLACES)
- 10. ALL UNMARKED HOLES ARE PLATED THRU.
- 11. BOARD TO BE PANELIZED AS A TABBED ARRAY. THERE SHALL BE NO SOLDERMASK OR BREAKAWAY TABS IN THE AREAS HIGHLIGHTED.

